REPORT ON CONDITION OF SURVEY MARK

STATE PA	COUNTY Lackawanna	QUAD NAME Scranton
----------	-------------------	---------------------------

STATION NAME and/or NUMBER TT 1 H QUAD NUMBER 166

LATITUDE N41° 17' 39"

TYPE OF MARK Transit Traverse Station

LONGITUDE W075° 37' 20"

YEAR ESTABLISHED 1943

ELEVATION <unknown> ft EST. BY: SUSGS NGS OTHER:

CONDITION See Remarks MARK STAMPED: TT 1 H 1943

REMARKS or REVISED DESCRIPTION: The disk was found in good condition but is in the wrong location. The chlorination plant is in ruins, but enough remains to determine that the boulder the mark is set in has been moved, possibly due to clearing for a woods road. The mark is now 22 feet at 104° magnetic from the center of the intersection of woods roads near the old plant. Also note that a Reference Mark disk has been used for this mark.

SUBMITTED BY: Jennifer K. Maher AGENCY: Individual DATE 4/13/2005

and Richard S. Galas