REPORT ON CONDITION OF SURVEY MARK

STATE PA COUNTY Lackawanna QUAD NAME Scranton

STATION NAME and/or NUMBER TT 2 H QUAD NUMBER 166

LATITUDE N41° 16' 35"

TYPE OF MARK Transit Traverse Station

LONGITUDE w075° 37′ 36″ YEAR ESTABLISHED 1943

ELEVATION <unknown> ft EST. BY: SUSGS STOTHER:

CONDITION Good MARK STAMPED: TT 2 H 1943

REMARKS or REVISED DESCRIPTION: Mark recovered in good condition, in top of boulder nearly flush with ground, in center of trail as described. Blazed trees were not found. Also note that a Reference Mark disk has been used for this station.

SUBMITTED BY: Jennifer K. Maher AGENCY: Individual DATE 5/29/2005

and Richard S. Galas